

2101 Jericho Turnpike, Box 5416 New Hyde Park, NY 11042-5416 **Phone:** 516-328-3970 · 1-800-819-3366 · **Fax:** 516-358-2576 Web site: www.technocnc.com · E-mail: support@technocnc.com

COLLETING GUIDELINES WRONG!

This picture shows an improper assembly. Notice the gap and angle of the collet in relation to the nut. The collet is not flush to the end of the collet nut. Correct this assembly before using.

DO NOT **PUSH THE** COLLET INTO THE SPINDLE AT **ANY TIME!**

Only the proper assembly should be screwed onto the spindle.



RIGHT!



The picture above is how your collet nut assembly should look: the end of the collet is flush with the bottom surface of the collet nut. You will hear and feel a "SNAP" as the collet properly goes into the collet nut. Once it is assembled, then "SCREW" the nut onto the threaded spindle end.



FOR TOOLCHANGE AND FIXED COLLET **SPINDLES:**

ONLY USE TOOLHOLDERS, **COLLET NUTS AND TOOLS** THAT ARE BALANCED TO **MEET OR EXCEED THE MAX RATED SPEED OF**



THE SPINDLE.



THE SPINDLE WILL BE DAMAGED IF **UNBALANCED EQUIPMENT IS USED!**